



## *MT 2000*

### Assembly tables




Assembly table for all work tasks on frames and sashes. Stable steel construction. Assembly table for all work tasks on frames and sashes. Table supporting surface with plastic slide bars. Storage tray for setting down tools and accessories. Adjustable height. Practical storage area under the table surface. Four PVC containers for small accessories, hardware and screws. 4-fold compressed air supply. Simple installation with a modular system design.




### Supporting surfaces

Supporting surfaces with plastic slide bars



### Storage tray

Storage tray for setting down tools and accessories




### Storage area

Storage area with four plastic trays for small accessories, hardware and screws




### Height adjustment

Adjustable height; working height can be set to 850 - 1.000 mm by means of adjustable feet



### 4-fold compressed air connection

4-fold compressed air connection for connecting compressed-air tools




### Castors (Optional)

Mobile unit: two casters with brake and two fixed rollers provide mobility in all directions




**Brush strip (Optional)**

Supporting surfaces with brush strip




**Felt strip (Optional)**

Supporting surfaces with felt strip




**Rubber strips (Optional)**

Supporting surfaces with rubber-knob profile



**Tool rack (Optional)**

Tool rack for pneumatic or electrical tools



**Maintenance unit (Optional)**

Maintenance unit for compressed-air tools



**Double two-pin grounded socket (Optional)**

**MT 2000 / ASSEMBLY TABLES****DIMENSION AND WEIGHT**

Length (mm)	2.000
Width (mm)	1.300
Height (mm)	850 ÷ 1.000
Weight (kg)	100

**SUPPORTING SURFACE**

Adjustable height	●
Storage tray for setting down tools and accessories	●
Table brush strip supporting surface	○
Table felt profile strip supporting surface	○
Table rubber knob profile	○

**CHARACTERISTICS**

Storage area under the table surface	●
PVC containers	4
4-fold compressed air supply	●
Tool holder	○
Service unit 1/4 with 4-fold air connections, Festo	○
Double two-pin grounded socket 230V 16A AP	○
Castor wheel Stand Alone (2 castors + 2 fixed)	○

Included ● Available ○